UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,744,409 B2 DATED

: June 1, 2004

INVENTOR(S): Grant A. Ellis

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 8,

Line 19, please add the following sentence after "... a single feed pin 200." -- The feed pin 200 is connected between the top plate 100 and a first end of a short length of transmission line 300, similar to the transmission line 30 shown in Figures 1A and 3B. --

Column 9,

Line 8, "... shorting pins connecting..." should be -- ... shorting pins directly

Line 17, change "... of claim 1, wherein..." to -- ... of claim 2, wherein... --

Signed and Sealed this

Sixteenth Day of November, 2004

JON W. DUDAS Director of the United States Patent and Trademark Office